0648A.M14400.

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
ROBERT J. WELCH ET AL.		:	Examiner: Ramon O. Ramirez
Appln. No.: 10/713,235		:)	Group Art Unit: 3632
Filed: November 14, 2003)	
For:	QUICK ADJUST SUPPORT SYSTEM WITH TRAPPED OR INTEGRAL WEDGE) :)	Certificate
U.S. Patent No.: 7,086,633 B2)	JAN 1 7 200, of Correction
Issued:	August 8, 2006)	January 3, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION **UNDER RULE 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/16/2007 SSANDAR1 00000003 061205 01 FC:1811

100.00 DA

7086633

Please charge the amount of \$100.00 in payment of the statutory fee for this Certificate of Correction, or any additional fee to Deposit Account 06-1206.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Ronald A. Clayton Attorney for Patentees

Registration No. 26,718

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 609532v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,086,633 B2

DATED

August 8, 2006

INVENTOR(S) :

ROBERT J. WELCH ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 11, "flipper, 18" should read --flipper 18--.

COLUMN 5:

Line 27, "my" should read --may--.

COLUMN 10:

Line 59, "FIG. 6A" should read --FIG. 6A,--.

COLUMN 13:

Line 26, "land" should read -- and --; and

Line 51, "hydro-forminging" should read --hydro-forming--.

COLUMN 15:

Line 40, "molded in" should read --molded-in--; and

Line 62, "wedge, member" should read --wedge member--.

COLUMN 16:

Line 30, "molded in" should read --molded-in--;

Line 59, "molded in" should read --molded-in--; and

Line 67, "molded in" should read --molded-in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY Main 609532v1 PATENT NO. <u>US 7,086,633 B2</u>

No. of add'l. copies @ 30¢ per page

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,086,633 B2

DATED

August 8, 2006

INVENTOR(S) :

ROBERT J. WELCH ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 40, "molded in" should read --molded-in--.

COLUMN 18:

Line 27, "a" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 609532v1 PATENT NO. <u>US 7,086,633 B2</u>

No. of add'l. copies @ 30¢ per page

